

st Report	No.:	SZXEC23001722917	Date:	Aug 03, 2023	Page 1 of 4		
Client Name:	SHENZHEN F	UICHIPS SEMICONDUCTO	OR CO.,LTD				
Client Address: 1/FEAST,BLOCK4,WANYAN(FUHAI)INDUSTRIALZONE,QIAOTOUCOMMUNITY,FUYON GSTREET,BAO'AN DISTRICT,SHENZHEN,CHINA							
Sample Name:	/						
Model No.:	C	0FN5060					
Client Ref. Information:		DFN5060,DFN1010,DFN2020,DFN2030,DFN2020,DFN3030,DFN3333, DFN6060,DFN8080,RUPAK8*8,QFN- 16/18/20/22/24/26/28/30/32/34/36/38/40/42/44/46/48/50/52/54/56/58/60					
The above samp	ole(s) and infor	mation were provided by the	Client.				
SGS Job No.:	S	ZP23-011974					
Sample Receivii	ng Date: J	ul 28, 2023					
Testing Period:	J	ul 28, 2023 ~ Aug 03, 2023					
Test Requested	: 5	select test(s) as requested by	/ the client.				
Test Method(s):	F	Please refer to next page(s).					
Test Result(s):	F	Please refer to next page(s).					
Test Requiren	nent				Conclusion		
Halogen				:	See Results		

Signed for and on behalf of SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Ford

Ford Shi Approved Signatory





Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <a href="http://www.sgs.com/en/Terms-and-Conditions/Terms-end-Cond

or email: <u>CN_Doccheck@asgs.com</u> Rom 101-901, Pant 24 Rom 101, Pant 38 Rom 101-501, Pant 3, Janghao (Bantian) Industrial Pant Area, No. 400, Jitua Rued, Bantian Community, Bantian Street, Longgang District, Stenchen, Guangdong, China 516129 www.sgs.group.com.cn 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江源(坂田) 工业厂区厂房4号101-901、2号101、3号301-501 都第:518129 t(86-755) 25328888 sgs.cohma@sgs.com



Test Report

No.: SZXEC23001722917

Date: Aug 03, 2023

Test Result(s):

Test Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A10	SZX23-0017229-0001.C010	"Semiconductor Device"(mixed)

Remarks:

(1) 1 mg/kg = 1 ppm = 0.0001%

(2) MDL = Method Detection Limit

(3) ND = Not Detected (< MDL)

(4) "-" = Not Regulated

Halogen

Test Method: With reference to EN 14582:2016, analysis was performed by IC.

Test Item(s)	Unit(s)	MDL	A10
Fluorine(F)	mg/kg	20	ND
Chlorine(Cl)	mg/kg	50	ND
Bromine(Br)	mg/kg	50	ND
lodine(l)	mg/kg	50	ND

Remark: The sample(s) was/were analyzed on behalf of the applicant as mixing sample in one testing. The above result(s) was/were only given as the informality value and only for reference. Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple

Acceptance Rule (w=0) stated in ILAC-G8:09/2019.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.ggs.com/en/Terms-and-Conditions.gapx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.gapx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.gapx and, for electronic Document, sax. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document, advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exconerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the comtent or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@gss.com

Room 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 3 & Room 301-501, Plant 3, Janghao (Bantian) Industrial Plant Area, No. 430, Jilua Road, Bantian Community, Bantian Street, Longgang District, Scherchen, Guangdong, China 516/29 www.sgsgroup.com.cn


t (86-755) 25328888 sgs.china@sgs.com 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江灏(坂田)工业厂区厂房4号101-901、2号101、3号101、3号301-501 邮编:518129



No.: SZXEC23001722917

Test Report ATTACHMENTS

Halogen Testing Flow Chart






Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.Yterms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's olice responsibility is to its Cilent and this document does not exconerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@egs.com

Room 101-901, Plant 4 & Room 101, Plant 3 & Room 101, Plant 3 & Room 301-501, Plant 3, Jianghao (Bantian) Industrial Plant Area, No. 430, Jihua Road, Bantian Community, Bantian Streed, Longgang District, Shenzhen, Guangdong, China 518129

中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江灏(坂田)工业厂区厂房4号101-901、2号101、3号101、3号301-501 邮编:518129 t (86-755) 25328888 sgs.china@sgs.com





SGS authenticate the photo on original report only *** End of Report ***



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions.Yterms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Cilent's instructions, if any. The Company's olice responsibility is to its Cilent and this document does not exconerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or faisification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN_Doccheck@egs.com

Room 101-901, Plant 4 & Room 101, Plant 2 & Room 101, Plant 3 & Room 301-501, Plant 3, Janghao (Bantian) Industrial Plant Area, No. 430, Jhua Road, Bantian Community, Bantian Street, Longgang District, Shenzhen, Giangdong, China 518129 www.sgsgroup.com.cn t (86-755) 25328888 sgs.china@sgs.com 中国・广东・深圳市龙岗区坂田街道坂田社区吉华路430号江灏(坂田)工业厂区厂房4号101-901、2号101、3号101、3号301-501 邮编:518129